




TEST AND FINAL INSPECTION CERTIFICATE	PAGE 4 of 4
---------------------------------------	---------------------------

CLIENT: [REDACTED]		REF/ORDER NO	TBA		DATE	4/12/2017	
TAG NO:		K3553-2			JOB NO.:		
VALVE TYPE		[REDACTED]			[REDACTED]		
DESCRIPTION:		Diaphragm - Piston			MEDIA SERVICE		
SIZE	20A -3/4"	MAKE	[REDACTED]	S/NO.:	[REDACTED]	DWG NO:	[REDACTED]
FIG NO.:	[REDACTED]	CLASS	[REDACTED] Pa <small>(PRESS./TEMP. TEST)</small>	STYLE	Screwd NPTF <small>(FLANGED: BUTT/SOCKET WELD)</small>	MAT'L BODY:	Bronze TRIM: Stainless & Resil

PERFORMANCE INSPECTION & TESTS

Test Media		Nitrogen		Service Media		[REDACTED]	
Test Pressure (Seat)		4,000	kPa	Working Pressure		120 - 150	MPa
Tests	Test gauge ID #	F10-922226-111516		Result	Passed	Failed	
Bubble Test: Nitrogen		Yes		Duration/Time	Secs	0 Bpm	Bubbles p/min
Holding Pressure:		4088	kPa	Test Comments		Good	
WORKSHOP REPRESENTATIVE				Valveman Inspector			
Signature:				Signature:			
Name:				Name:			
Place of Inspections:		Unanderra, NSW		Date of Test & Certificate Issued		31/05/2018	

Certificate Number	VT318615.K4971	Original / Copy
--------------------	----------------	-----------------



Acceptance Criteria: Refer where applicable for SRVs, eg API Standard 598, API Standard 527, AS 1271 or the Valve/Manufacturers Standard and/or the Clients specifications.

For internal inspection condition refer to VRIS form - If Actuator installed - min cycling required - 3 times prior each test.

NB. Original certificate marked in Blue